THREE PHASE O/U VOLTAGE O/U FREQUENCY MICROPROCESSOR RELAY


TYPE

MC3V

Addendum

Connection on 2 PT

Wiring Diagram (Connection on 2 PT)



With this connection, the secondary rated voltage of the PT (see wiring diagram) must be set at the rated phase-to-phase voltage multiplied by 1.73.

Ex.: PT 1000/100

V1n = 1000V2 = 173

Notice that in this connection the set zero sequence voltage can not be measured therefore the "Uo>" element must be set to "Dis" (Disable).